


INSTALLATION AND WIRING DIAGRAM

USA

ORION SERIES LEDS

ORION AL-C

ART. NO. 135 301/c	clear, LED white	135 303/c	clear, LED green
135 301/f	frosted, LED white	135 303/f	frosted, LED green
135 301-1/c	clear, LED white	135 304/c	clear, LED red
135 301-1/f	frosted, LED white	135 304/f	frosted, LED red
135 302/c	clear, LED blue	135 305/c	clear, LED amber
135 302/f	frosted, LED blue	135 305/f	frosted, LED amber



IMPORTANT SAFETY INSTRUCTIONS



1. THIS PRODUCT MUST BE INSTALLED BY A PERSON FAMILIAR WITH THE CONSTRUCTION AND OPERATION OF THE PRODUCT AND THE HAZARDS INVOLVED, IN ACCORDANCE WITH LOCAL NEC CODE.
2. This product MUST BE HARD WIRED. For all the wire connections, use UL Listed Wire Nuts.
3. Must use UL listed 1/2" conduit (not provided).
4. SUITABLE FOR SUSPENDED CEILING.
4. Turn off power prior to any work on the systems.
5. Warranty is void in case of unauthorized modifications and/ or improper use.

READ ALL OF THESE INSTALLATION INSTRUCTIONS BEFORE INSTALLING THE FIXTURE

Contents of Delivery: ORION AL-C - qty. (1)

Step1

- Drill a 1-9/16" hole into the mounting surface.

Step2

- Connect white, black and ground wires (A) from the conduit to the wires from the AL-C using UL listed wire nuts. The wire nuts should be tucked into the wiring compartment (C).

Step3

- Attach the conduit (B) into the AL wiring compartment (C).

Step4

- Unscrew the set screw (E) from the AL cover (F) and unscrew the cover from the base (D). The rubber gasket (G) must be used at the bottom of the product before it is secured to the mounting base. Align the base with the rubber gasket (G) so that the mounting screws (H) will go through. Screw the base (D) to the mounting surface.

Step5

- Screw the AL cover (F) securely onto the base (D) and tighten the set screw (E) to complete the installation.

